

# Oil Field Environmental Incident Summary

**Incident:** 20150305091544      **Date/Time of Notice:** 03/05/2015 09:15

**Responsible Party:** CONTINENTAL RESOURCES, INC.

**Well Operator:** CONTINENTAL RESOURCES, INC.

**Well Name:** MADISON 3-28H

**Field Name:** DOLLAR JOE

**Well File #:** 24382

**Date Incident:** 3/4/2015

**Time Incident:** 10:00

**Facility ID Number:**

**County:** WILLIAMS

**Twp:** 155

**Rng:** 97

**Sec:** 21

**Qtr:**

**Location Description:**

**Submitted By:** Shane Knuchel

**Received By:**

**Contact Person:** Shane Knuchel  
PO BOX 268870  
OKLAHOMA CITY, OK 73126

**General Land Use:** Well/Facility Site

**Affected Medium:** Topsoil

**Distance Nearest Occupied Building:**

**Distance Nearest Water Well:**

**Type of Incident** Other

**Release Contained in Dike** No

**Reported to NRC:** No

	Spilled	Units
Oil	0.3	Barrels

Recovered	Units
-----------	-------

Followup	Units
----------	-------

Brine

Other

**Description of Other Released Contaminant:**

**Inspected:**

**Written Report Received:**

**Clean Up Concluded:**

**Risk Evaluation:**

None

**Areal Extent:**

Approximately 150x25 feet swath SE of well site onto another CLR well site was misted.

**Potential Environmental Impacts:**

Minimal after clean-up.

**Action Taken or Planned:**

Contaminated soil and vegetation will be removed.

**Wastes Disposal Location:** TBD

**Agencies Involved:** Notified Tammy Cook NDIC by text message at 2:48 PM CT

**Updates**

---

**Date:** 3/5/2015      **Status:** Reviewed; Followup Required      **Staff:** Stockdill, Scott

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

According to the incident summary, this spill impacted areas off of location. Followup is necessary.

---

**Date:** 3/12/2015      **Status:** Awaiting Documentation      **Staff:** Martin, Russell

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

3/12/2015 at 16:02, on location. Wheat stubble field has been scraped along northern border with wellpad. There is no visible staining on remaining stubble and no sheen visible in meltwater accumulating in field. Report contact will be taking confirmation samples and sending them to the NDDoH.